

Pulsar PGDA70BiSCO - Part Number Discrepancies

While going through the parts PDF I found a few parts where the main summary table and the detailed subassembly pages list different numbers for the same part. The numbers I used in my request spreadsheet are the detailed subassembly numbers (the right column below). If your system shows any of these as superseded or replaced by a current number, please use the correct current one.

Part	Summary table number	Detailed subassembly number (used in my request)
Spark Plug	2160.168.008V.00.00	2160.168.006V.00.00
Carburetor Assy	2260.F80.0031.00.00	2260.F80.0220.00.00
Air Cleaner Assy	2280.F80.0020.00.00	2280.F80.0030.00.00
Recoil Starter Assy	2000.T70.0020.00.02	2000.T70.0040.00.02
Gasket, Intake to Cylinder Head	3060.F80.001V.00.00	3060.F80.0020.00.00
Gasket, Carburetor to Intake Manifold	3080.F80.001V.00.00	3080.F80.0020.00.00
Spacer, Intake Manifold	2300.F80.001V.00.00	2300.F80.0020.00.00
Self-Tapping Screw	0845.35095.00.07	0845.35095.00.01

Note: the Recoil Starter Assy is listed here only so the number is clear. I am not requesting the complete recoil assembly unless you would rather send it whole; the damaged recoil parts I need are the handle, the grip pocket, and the rope guide.