

PGDA70BiSCO Parts Request
Submitted to Pulsar Products Inc. by Lonnie Barkby on June 30, 2026, at the request of Pulsar representative Roy (service04). Pulsar [case reference redacted] / [return reference redacted]. Converted from the original spreadsheet for filing; contents unchanged.

Parts Request

Pulsar PGDA70BiSCO - Parts Request
(Lonnie Barkby)
Numbers below use the detailed subassembly pages. Where the summary table differs, please substitute the current Pulsar number.

Part Description	Part Number	Qty	Group	Notes
REPAIR PARTS - active failures and physically broken parts				
Electric Start and Charging Starter Motor Assy	2070.F80.A041.00.00	1	Repair	Click but no crank. No separate solenoid/relay listed in diagram.
Lithium Battery	2461.188.001V.00.00	1	Repair	Can read normal voltage and still fail under load.
Voltage Regulator	6854.528.0021.00.00	1	Repair	Charging only rose 13.28V to 13.32V running - points at charging side.
Battery Wiring Harness	6951.528.0030.00.00	1	Repair	
Battery Strap	9575.J24.0010.00.00	1	Repair	Only if battery is sent.
Battery Protection Pads	2757.562.0010.00.00	4	Repair	Only if battery is sent.
Control and Output Panel	3370.J24.0270.00.99	1	Repair	Conditional: diagram does not list a separate starter relay/control module. Send or

substitute

control

Recoil-Start Side and Cracked Left Panel (all broke in the same pull)				
Handle, Recoil Starter	2000.T70.001V.00.03	1	Repair	Rope knot pulled through the handle.
Pocket, Recoil Starter Grip	7495.528.0020.00.00	1	Repair	
Guide, Recoil Rope	2186.T48.001V.00.00	1	Repair	Cracked in the same incident.
Left Side Panel	5590.J24.0020.93.00	1	Repair	Cracked when the rope whipped back.
Rubber Grommets	5522.467.002V.00.00	4	Repair	Left panel mounting.
Phillips #2 Pan Head Screw	0818.05016.00.07	5	Repair	Left panel fasteners.
Bolt M6x16	5787.06016.00.07	2	Repair	Left panel fasteners.
Nut M5	6178.05000.01.04	9	Repair	Left panel fasteners.
Telescoping Handle and Surrounding Housing (handle confirmed covered)				
Telescoping Handle Assy	9874.J24.0010.00.00	1	Repair	Broken / damaged.
Grab Handle Tube, Fixed	4821.J24.001V.D7.00	1	Repair	
Handle Tubes Bracket	8324.J24.001V.D7.00	1	Repair	
Handle End Washer	8795.J24.0010.00.00	1	Repair	
Rubber Plug	5010.562.004V.00.00	4	Repair	
Upper Shell of	9674.J24.0010.00.00	1	Repair	May have to come off to reach the handle; risk cracking during disassembly.
Gasoline Tank Apron	3275.J24.0010.00.00	1	Repair	Same - disturbed during handle replacement.
Self-Tapping Screw	0845.35095.00.01	2	Repair	Handle fasteners.
Self-Tapping Screw	0845.42016.00.01	4	Repair	Handle / upper shell fasteners.
Self-Tapping Screw	0845.42012.01.01	4	Repair	Handle / upper shell fasteners.
Phillips #2 Pan Head Screw	0818.05016.00.07	4	Repair	Handle / upper shell fasteners.
Bolt M6x12	5787.06012.00.07	5	Repair	Handle / upper shell fasteners.
Bolt M6x16	5787.06016.00.07	1	Repair	Handle / upper shell fasteners.
Nut M5	6178.05000.01.04	2	Repair	Handle / upper shell fasteners.

ADDITIONAL PARTS REQUESTED - common wear / failure items, given this unit's history				
Spark Plug	2160.168.006V.00.00	1	Spare	Ethanol gum risk.
Carburetor Assy	2260.F80.0220.00.00	1	Spare	
Gasket, Intake to Cylinder Head	3060.F80.0020.00.00	1	Spare	
Gasket, Carburetor to Intake Manifold	3080.F80.0020.00.00	1	Spare	
Spacer, Intake Manifold	2300.F80.0020.00.00	1	Spare	
Gasket, Air Cleaner to Carburetor	2340.188.001V.00.00	1	Spare	Ethanol hardens/cracks rubber lines.
Fuel Filter Screen	7080.165.001V.00.00	1	Spare	
Gasoline Debris Filter	3200.168.075V.00.05	1	Spare	
Fuel Line	2330.528.C110.00.23	1	Spare	
Fuel Supply Line to Carburetor	2330.528.C021.00.21	1	Spare	
Fuel Line Sleeve	2332.168.001V.00.00	1	Spare	
Hose Clamp	2360.458.R003V.00.00	2	Spare	
Hose Clamp	2360.458.R004V.00.00	1	Spare	
Gasoline Tank Outlet	3206.168.R001V.00.00	1	Spare	
Oil Drain Bolt Gasket	1260.168.R001V.66.00	2	Spare	
Valve Cover Gasket	3000.F80.001V.00.00	1	Spare	Only if the filter element is NOT sold separately.
Valve Cover Vent Gasket	7061.F80.002V.00.00	1	Spare	
Muffler Exhaust Gasket	3100.188.004V.00.00	1	Spare	
Air Cleaner Assy	2280.F80.0030.00.00	1	Spare	
			(conditional)	